



Department of Transportation

ANDREW M. CUOMO
Governor

MARIE THERESE DOMINGUEZ
Commissioner

May 15, 2020

OPERATOR ID 01618

LAKE PLACID CENTRAL SCHOOL
50 CUMMINS RD
LAKE PLACID, NY 12946

Dear Motor Carrier:



Enclosed is the annual New York State Department of Transportation Bus Inspection System Operator Profile that summarizes the results of vehicle inspections performed on your fleet by the Department during the last State Fiscal Year (April 1, 2019 to March 31, 2020). For regular inspections, the profile identifies the number and percentage of vehicles that passed or were placed Out-of-Service (OOS) due to one or more OOS defects. It is the Department's continued goal to have all operators pass at least 90% of their scheduled safety inspections. The current statewide average OOS rate is 4.6% (95.4% pass rate).

We congratulate those operators who have achieved the goal of a 90% or greater pass rate. Your commendable performance indicates a strong dedication to safety and a commitment to sound maintenance standards and practices.

Operators who have a passing rate of less than 90%, it is requested that your organization examine the enclosed profile inspection data and immediately update your maintenance program in order to achieve the Department's stated goal. Your Regional Bus Inspection Program Supervisor is available to review the actions being taken and provide assistance, if necessary, to address any needed changes.

For those operators whose OOS rate is 25% or greater and fall under the Department's enforcement program, you will be contacted shortly to address your unacceptable poor performance. Actions include, but are not limited to, civil penalties, unannounced vehicle inspections, denial of B & C privileges, and compliance reviews.

You can find contact information for the Supervising Motor Vehicle Inspector in your area at:
<https://www.dot.ny.gov/divisions/operating/osss/bus/contact-list>

Please visit <https://www.dot.ny.gov/divisions/operating/osss/bus> for program updates.

New York State Department of Transportation
Office of Modal Safety and Security
Passenger Carrier Safety Bureau



Department of Transportation

BUS INSPECTION SYSTEM OPERATOR PROFILE

April 16, 2020
Operator: 01618

Profile Period: 04/01/2019 to 03/31/2020

LAKE PLACID CENTRAL SCHOOL
50 CUMMINS RD
LAKE PLACID, NY 12946
Operator Category Status: Preferred

OUT OF SERVICE RATE FOR THE PROFILE PERIOD ABOVE IS:

0.00%

(This rate reflects the results from full and critical item inspections for this operator only. Failed inspections occur when at least one "A" defect is identified)

INSPECTION PERFORMANCE

Inspection Summary of Full and Critical Item Inspections:

	<u>Total</u>	<u>Percent</u>
Inspections:	27	
Passed (With No "A" Defects):	27	100.00%
Failed (With At Least 1 "A" Defect):	0	0.00%



Department of Transportation

BUS INSPECTION SYSTEM OPERATOR PROFILE

April 16, 2020

Operator: 01618

Profile Period: 04/01/2019 to 03/31/2020

LAKE PLACID CENTRAL SCHOOL

50 CUMMINS RD

LAKE PLACID, NY 12946

Operator Category Status: Preferred

DETAIL SUMMARY

<u>Inspections</u>	<u>Total</u>
Full Inspection	13
Critical Above	11
Critical Below	3
Re-Inspection	0
Post Accident	0
Fleet	0
Random	0
New in Service	0
Distributor	0
Special	0

<u>Non-Inspection Transactions</u>	<u>Total</u>
Non Present	0
Temp OOS	0
Perm OOS	3
Certificate Replacement	0
Transfer	0
Misc.	0

DEFECT SUMMARY (Full or Critical Inspections Only)

<u>Item</u>	<u>Total</u>
Maintenance Records	
53.00-1-N MAINTENANCE & RECORDS:MAINTENANCE & RECORDS	17
Records Not Presented	0
PMI Exceeded	0
PM Records Incomplete	0
DVIRs Not Presented	0