



OPERATOR ID 02388

TUPPER LAKE CENTRAL SCHOOL
25 CHANEY AVE
TUPPER LAKE, NY 12986

Dear Motor Carrier:

Enclosed is the annual New York State Department of Transportation Bus Inspection System Operator Profile that summarizes the results of vehicle inspections performed on your fleet by the Department during the last State Fiscal Year (April 1, 2024, to March 31, 2025). For regular inspections, the profile identifies the number and percentage of vehicles that passed or were placed Out-of-Service (OOS) due to one or more OOS defects. It is the Department's continued goal to have all operators pass at least 90% of their scheduled safety inspections. The current statewide average OOS rate is 4.1% (95.9% pass rate).

We congratulate those operators who have achieved the goal of a 90% or greater pass rate. Your commendable performance indicates a strong dedication to safety and a commitment to sound maintenance standards and practices.

Operators who have a passing rate of less than 90%, it is requested that your organization examine the enclosed profile inspection data and immediately update your maintenance program in order to achieve the Department's stated goal. Your Regional Bus Inspection Program Supervisor is available to review the actions being taken and provide assistance, if necessary, to address any needed changes.

For those operators whose OOS rate is 25% or greater and fall under the Department's enforcement program, you will be contacted shortly to address your poor performance. Actions include, but are not limited to, civil penalties, unannounced vehicle inspections, denial of B & C privileges, and compliance reviews.

You can find contact information for the Supervising Motor Vehicle Inspector in your region here:

<https://www.dot.ny.gov/divisions/operating/osss/bus/contact-list>

Please visit <https://www.dot.ny.gov/divisions/operating/osss/bus> for program updates.

Passenger Carrier Safety Bureau
Office of Modal Safety and Security
New York State Department of Transportation



Department of Transportation

BUS INSPECTION SYSTEM OPERATOR PROFILE

April 24, 2025

Operator: 02388

TUPPER LAKE CENTRAL SCHOOL

25 CHANEY AVE

TUPPER LAKE, NY 12986

OUT OF SERVICE RATE FOR THE PROFILE PERIOD ABOVE IS:

2.13%

(This rate reflects the results from Full and Critical Item inspections for this operator only.
Failed inspections occur when at least one "A" defect is identified)

INSPECTION PERFORMANCE

Inspection Summary of Full and Critical Item Inspections:

	<u>Total</u>	<u>Percent</u>
Inspections:	47	
Passed (With No "A" Defects):	46	97.87%
Failed (With At Least 1 "A" Defect):	1	2.13%

April 24, 2025
Operator: 02388

TUPPER LAKE CENTRAL SCHOOL
25 CHANEY AVE
TUPPER LAKE, NY 12986

DETAIL SUMMARY

<u>Inspections</u>	<u>Total</u>
Full Inspection	21
Critical Above	10
Critical Below	16
Re-Inspection	1
Post Accident	0
Fleet	0
Random	0
New in Service	0
Distributor	0
Special	0

<u>Non-Inspection Transactions</u>	<u>Total</u>
Non Present	0
Temp OOS	0
Perm OOS	1
Certificate Replacement	0
Transfer	0
Misc.	0

DEFECT SUMMARY (Full or Critical Item Inspections Only)

<u>Code</u>	<u>Item</u>	<u>Total</u>
"A" DEFECTS		
21.00-2-A	EMERGENCY WINDOWS/ROOF HATCHES:2. FAILS TO FUNCTION CORRECTLY	1
"C" DEFECTS		
18.03-3-C	STEPWELL:3. STEPWELL LIGHT INOPERATIVE	1
Maintenance Records		
52.08-1-N	BRAKE TEST NOT PERFORMED:DUE TO UNSAFE ROAD CONDITIONS	12
Records Not Presented		0
PMI Exceeded		0
PM Records Incomplete		0
DVIRs Not Presented		0